5X1	Sanitized	Copy Approved for Relea	se 2009/12/17 : CIA-RDP69B00041	R002200030009-3
			To 100 (100 (100 (100 (100 (100 (100 (100	o: H-24 <u>//00</u> L
		CONSOLIDATI	D CHECK LIST	
5 X 1	1. MESS	AGES:		Msg File No.
	OUT:			
5X1	ıń:	NLT H-25 from WH	KEN Action/DCNW	
X1		applicable to	only for Area-ORIT	
X1		NLT H-24 from	Info/DCOC	#2
		NLT H-24 from	ction/CMDR, DCOC & COMMO	<u># 1</u>
. .	2. AIRCRAFT G	ENERATION CHECK LIST:		
	•			
	2 CHOMITANG	OH OW Trom		
X1		CH_CK LIST:	,	COMP
^ 1	Command Po	st/ receive Complete mission	initiate 24-hour operation. alert notification and notify	-
		personnel of Comm	ander's briefing. Convert	
		record on appropr	cal and Zulu time; determine iate H-hour page. Determine	and record
		on appropriate H-	hour page, and message traffir transmission of the followi	c log
5X1		page j care came to	0930 h	 R
5X1		Da	ily NLT 0900L Action/DCOTB	
)		Da.	ily NLT 1100Z Action/DCM	
		n _a .	1800L ily NLT 1100Z Action/DCM	
		Da.	TA MIT THOUS ACTIONS DOM	

VP to H-24

25 YEAR RE-REVIEW

						. *	10:	H-23/ 1200 L
				CONSOLIDAT	ED CHECK LIST			
	1.	MESSAGES:				÷		Msg File #
		OUT:						
25 X 1								
20/1		IN:	NLT H	-23 from	Action/DCO	W,DCO,	and DCOC	<u> </u>
	2.	AIRCRAF T G EN	VERATION (CHECK LIST:				Start Comp.
		At/From	To	CL#	Section/Act	ivity		
C.	-				ige t	م		
	3.	SECTION CHEC	K LIST:		change ASAP blish H-hour t			
		H-24:00 1100 L		cler.	blish H-hour t ks to Mission until mission	Coordi	inator fro	om.
		H-23:00 1200L		SECURITY	/Hangars secur Posted.	red; ac	ccess list	B)
		H-23:30 (1130 L)	Com	nauders	INITIAL Bri	iefing		
G	٠ .	1130 - 12	30	Secent A	incraft & Ass	ich pr	TEKAGE	
		1130	Maior	. SECUTÉ	Nitrogen, O	xyger		

Sanitized Copy Approved for Release 2009/12/17: CIA-RDP69B00041R002200030009-3

H-24:00 to H-23:00 TOP SECRET

	<u>T.</u>	OP SECRET	From:	H-23/ 1200
	CONSOLI	DATED CHECK LIST	To:	H-22/1300
MESS.	ACES:			MSG FILE #
OUT:				
IN:	NLT H-22 From	Action/DCOC		# 6
	NDT H-22 From	Action/COMMO & DDC	oc	#5
	NLT H-22 From	Action/EWS		#9
2. AIRCRAFT GE From/At To H-22:30	ENERATION CHECK LIST: CL# Section/Activi 8 DDCM/Start mis			start/end. Start Con
			age for	
From/At To	CL# Section/Activi	<u>ty</u>		Start Com
From/At To	CL# Section/Activi	<u>ty</u>		Start Con
From/At To	CL# Section/Activi	<u>ty</u>		Start Con
From/At To	CL# Section/Activi 8 DDCM/Start mis	<u>ty</u>		Start Con
From/At To H-22:30 3. SECTIONS CH	CL# Section/Activi 8 DDCM/Start mis: HECK LIST: 1:30) 2 FLT SURG/Pre-	<u>ty</u> sion aircraft pre-flig	ht	Start Con
From/At To H-22:30 3. SECTIONS CH H-22:30 (H-21)	CL# Section/Activi 8 DDCM/Start miss HECK LIST: 1:30) 2 FLT SURG/Pre-ipilot; Inform	ty sion aircraft pre-flig	ht	Start Con

H-23 to H-22

		S	anitized Copy	Approved for Rele	ase 2009/	12/17 : CIA-RE)P69B00041 rom:	R00220003 H-22/ <u>13</u>	30009-3 1
				CONSOLIDA	TED CHEC	K LIST	To:	H-21/14	-00 L
25 X 1	1.		MESSAGES:					Msg F	ide #_
25 X 1		OUT:			ction/DC				#5
25 X 1		IN: (NLT H-21 from	SAC :	Info/DCOTC	>		<u>#1</u>
				NLT H-21 from	WECEN	Action/DCOW			<u># 15</u>
				NLT H-21 From	WECEN A	Action/DCOW			#14
	2.	AIRCR/	AFT GENERAT	ION CHECK LIST:					
	3. <u>From</u>	Tim	NS CHECK L.	IST: () see app		page for s	tart/end.	Start	Comp
	(H-:		H-21:30 (+330L)	2 FLT SURG/P	re-missio	n physical e	exam of ator of	Mileton Company	L
	H2	2 (H-1)		The same of the sa		es and Equi		<u>~</u>	
		1300	L	should ge	on p	evious p	igi		
C	ال								
25X1 ¹ 25X1		*Ver as st	ify package tated in	loading with DD	CM, repor	t in commen	ts	if oth	ner than

		Sanitized C	ору Ар	proved for Releas <u>TOP_SEC</u>				H-21/ <u>14</u> C	
				CONSOLIDATED	CHECK LIST		To:	H-20/ <u>150</u>	00_L
25X1		MLSSAGES:	۰					Msg Fi	le #
-•∣ 25X1	OUT:	THIODICALE.	Intent	ions Alert Msg	NLT H-20:0	O Action,	/DDCOC	OUT	·
	IN:								
			mTON (HECK LIST: ()	cee ann ron	riate na <i>g</i> e	e for st	art/end.	
2. Fr	AIRCI om/At	AFT GENERA To		Section/Activ		Trans bad		Start	Comp
		12/ AAA		DCM INS Prest					
3.		IONS CHECK	LIST:						
	-20:00 1500 L		5	COMMO/Notify channelizatio	DCM of UHF n, and tran	frequency aslator co	change: des.	3,	<u>~</u>
25 X 1	12081 -50:00 1000 5	\sim		DDCOC/Send	Int	tentions A	lert Me	ssage	<u> </u>
					•		11		

Sanitized Copy Approved for Release 2009/12/17: CIA-RDP69B00041R002200030009-3 rrom: n-20/15/00 L

CONSOLIDATED CHECK LIST To: H-19/1600 L

MESSAGES:

OUT:

1N:

2. AIRCRAFT GENERATION CHECK LIST: () see appropriate page.

From/At To CL# Section/Activity

H-21:001 The Comp

The Comp

H-21:001 The Comp

Th

AFCS/Personnel released for crew rest

SECTIONS CHECK LIST:


H-19:00

1600 h

	Sanitize	d Copy Approved for Rele	ase 2009/12/17 : CIA	\-RDP69B000	041R00220003	30009-3
		TOP S	SECRE T	From:	H-19/ <u>160</u>	<u>о</u> т
				To:	H-18/1700	L
		CONSOLIDATED (CHECK LIST			
25X1 _l .	• MESS	AGES:			Msg File #	<u> </u>
	OUT:					
				•		
25X1	IN:	NLT H-18 from	Action/DCOMF	· · · · · · · · · · · · · · · · · · ·	4	
		NLT H-18 from	Action/DCOMI		10	•
		NOT H-18 from Mic	EN Action/DCOM		· ·	e e e
ر_2.	AIRCRAFT G	ENERATION CHECK LIST:	() see appropr	iate page.	, e	* *
	From/At	To CL#	Section/Acti	vity ,	Start	Comp
* •	H-18	Start INS	juflight #	1	1800	<u> </u>
3.	SECTIONS C		#		0900	
		# 1 delayed bee he hanger.	ause of pour	uer pro	blema	
	int	h hanger.				
)		y				

	Sanitized Copy App	roved for Release <u>TOP_SEC</u>			H-18/ <u>1700</u>	
		CONSOLIDATED	CHECK LIST	To:	H-17/ 1800	
25X1 ₁ .	MESSAGES:				MSG	FILE #
OUT:						·
25X1 IN:		• "	from WECEN Ac from WECEN Ac	tion/DCOW	<u></u>	5
2. AIRCR	AFT GENERATION C	POYT CONFIRM	1	730 ACTION/DCO M/C	#	16
iom/At	To CL#	Section/Activity		te page	Start Co	omp_
(H-19:00) 1600 - H-17 (M-1 1800	H-17:00 17 1800 5)	Move AC for T				P s
3. <u>SECTI</u> (H-22:00)	ONS CHECK LIST:	DOOT (and and				
H-18 H-1	•	DCOL/end prefli			comp	
♂						
	*.	H-18 to	H -1 7		TOP SECRET CP 66-TS-08	34

		Sai	nitized Copy	Approved to	or Releas	se 2009/12/1	7 : CIA-RL)P69B0004	41R00220	0030009-3	ملى 3
				CONSOL	IDATED C	HECK LIST			To; H-1	.6/ <u>1900</u>	L
25 X 1	1.		MESSAGES:				e e		MSG	FILE #	
25 X 1		OUT:		21	NLT	1800 h	ACTION	DCM			
				30	ALT	1800 h	,	$\hat{\boldsymbol{\theta}}$			
		IN:		_					•		·
	2.	AIRCR	AFT GENERA	PION CHECK	LIST:	() see a	pp ropria	te page.			
	Fro	m/At	To	CL#	Section	n/Activity	<u>r</u>		Start	Comp	
	d .	H- H-	16 e	omplete Stent	INS EWS	prefly	ght (Ir	Em 16) #1	1645	<u>></u>	
	3.	SECTI	ON CHECK L	IST:		0 0 (Q and a	#2	7630		
	(H-)	6:35_(H-25:00)		DCOM/	Rec R 76 v	ia 1604				-
		INS prob	prefle	ght o. Hange	~ 121 chal	7 war ND-4's	dela	yed d	ue to	power	
25 X 1\		_			lermin	wlogy	Eit	wor	mode	- od	
<u>ر</u>) .	Big	Blank	inated	ed og	modi	LI			D	
				•							
25X1						e e e e e e e e e e e e e e e e e e e					Mayeti




H-16 to H-15

	Sa	anitized Copy	Approved for Release 20)09/12/17 : CIA-RDF	P69B00041R00	02200030009-3	L
			CONSOLIDATED CHECK I	LIST	To: H-	4/2100	L
5 X 1	1.	MESSAGES:				MSG FILE #	
	OUT:						•
5X1 5X1	IN:		NLT H-14 from	Action/DDCOM &	DDCOC	Strategic Control of the Control of	
			NLT H-14 from WECEN	Info/DDCOW			•
	2. AIRCR	AFT GENERAT	TION CHECK LIST:				•
	From/At	To CI	# Section/Activit	X	Start	Comp	
5X1	H-15:00	H=14:00	19 DDCM/Move acit	to		P s	
	3. SECTI	ONS CHECK L	IST: () see approp	riate page.			
	H-14:00		DDCOMI/Give sur	vival packet to	DCOL	comp	
	H-15:00	to (H-8:0	DDCOM/Prepare co	omplete map stri	p <u></u>	·	•
	H-14:00		DDCO/FOR Steel I with STFC on nur	Bridge: Coording	ate required.	complet	٤

	San	itized Copy A	pproved fo	or Release	2009/12	′17 : CIA-F	RDP69B00	041R002	2000300	009-3 L
	. '			IDATED CH				H-13/		
5 X 1	1.	MESSAGES:							MSG F	ILE #
,	OUT:									
!										
5X1	IN:		NLT H-1	3 from		Info DDC	OM & DDCC	C		
	2. AIRC	RAFT GENERA	TION CHEC	CK LIST:	() see	∍ appropi	riate pag	e.		·
	From/At	<u>To</u>	<u>CL#</u>	Section/	Activity	L		Sta	art .	Comp
	A-14:00	(H-10:	30) 20	DDCM/8€	art pack	age load	for acf	ts	P	
	H-13	Comple	te Ews	puflig	ht #1		(Irem11)		S	
	H= 13	stenst	phg	load	#	^	# 20			
	3. SECT	IONS CHECK	_		#2	·		6		
	H-13:00			DDCM/To	assign	the two	A-12 acf	to		
5 Y 1				DCO (fo	المران ما	ion in	we grie in	ACTTA		

Sanitized	TOP SECRET			2200	L
	CONSOLIDATED CHECK	LIST	Fo: H-12/	2300	_L
25X1. MESSAGES:	:			MSG FI	LE#
25X1 OUT:	Support Requirement Msg NI	T H-12:00 Action,	/DDCOC	·	
25X1	NLT H-12 from SAC In	fo/Doorc			
2. AIRCRAFT GENERA	ATION CHECK LIST:		: :		
From/At To	CL# Section/Activity		<u>st</u>	art Com	<u> </u>
		•	• .	•	
3. SECTIONS CHECKI	LIST: 15 DCOMF/Give DCOC nav				
H-12:00	5 DCOC/Coordinate with ADIV notification to format	th COMMO & DCOMF of tion and submit ad to 313 ADIV on not	vance) _	
	ve must set uy	, a format	- and	atiek	
to to is	X.				
			l		
				. ,	

	S	anitized Copy A	pproved for Release	2009/12/17 : CIA- பாட்ட	RDP69B00041	R002200030009-3 H-1 <i>2/<u>み</u>うUU</i> _L
			CONSOLIDATED	CHECK LIST	To:	H-11/2400 L
25X1 _l	•	MESSAGES:				MSG FILE #
	OUT:					
2	IN:	AFT GENERATIO	N CHECK LIST: () see annronris	ate nage	
	rom/At		L# Section/Activ		oo pago.	<u>Start Comp</u>
0	- <u>12:00</u> H-1		DCM/SIP insta tar checks	Lled, checked o	out & Beacon	P s
3	. SECTION	ONS CHECK LIS	<u>r</u> :			
	-12:00	(H-4:30)	7 FLT SURG/Pilot	s aslee		-
25X1 _{N-}	-17:30_		1 SOMMO/Send	(NLT H-1	.0)	<u> </u>



	S	anitized Copy Approved for Release 2009/12/17 : CIA	A-RDP69B00041R002 T0:	200030009-3 L
05)/4		CONSOLIDATED CHECKLIST		
25X1	ı.	MESSAGES:		MSG FILE #
		IN:		
	,	OUT:		
	2.	AIRCRAFT GENERATION CHECKLIST:		
	3.	SECTION CHECKLIST:		

TOP SECRET (when filled in)

